

# MANHOLE INSPECTION REPORT

MH NUMBER	PROJECT	OWNER
A3	Sample City, AL	Sample City, AL

ACCESS TYPE	SURVEYOR	DATE	DRAINAGE AREA	SHEET NUMBER
Manhole	DM/UC	Sep 9, 2019		2

ADDRESS	CITY	LOCATION CODE	PURPOSE OF SURVEY
234 Main St	Midland City, AL	Woods	B-I&I Investigation

SURFACE TYPE	RIM TO INVERT (VF)	ACCESS TYPE	PRE-CLEANING
Grass/Dirt	5.6	Manhole	N-No Pre-Cleaning

MANHOLE USE
Sanitary Sewer

COVER	
Type:	Solid
Shape:	Circular
Size (in):	19
Material:	Cast Iron
Condition:	Corroded

FRAME	
Material:	Cast Iron
Condition:	Sound

CONE	
Material:	Concrete (precast)
Condition:	Sound


CHANNEL	
Present:	Yes
Condition:	Sound

CHIMNEY	
Present:	Yes
Material:	Brick
Condition:	Sound

WALL	
Material:	Concrete (precast)
Condition:	Sound

BENCH	
Bench Present:	Yes
Condition:	Sound

ADDITIONAL INFO
None



# MANHOLE INSPECTION REPORT

MH NUMBER

A3

SURFACE IMAGE #1



SURFACE IMAGE #2



# MANHOLE INSPECTION REPORT

MH NUMBER

A3

INTERIOR IMAGE #1



INTERIOR IMAGE #2

